

Generally, the microstep method provides the most precise controlling method. However, among the three approaches explained here, the 1&2-phase-on is the method with the most precise control.